



Area of application



ESC international



Document details



Document ID	ESC_HSE-Warning_2015-13_Retractable-type-fall-arrester-Blocfor10AES_Rev000_de-en.docx		
Confidentiality	ENERCON Partner		
Date	Language	DCC	Plant/department
2015-12-10	en	QB	Service Deutschland GmbH/Health & Safety



Revision details



Revision	Date	Section	Change
000	2015-12-10	-	Document created



Topic



Retractable type fall arrester BLOCFOR 10 AES by Tractel



Areas concerned



Installation / Service



Description



- Tractel Greifzug has informed us about a possible problem with retractable type fall arresters model BLOCFOR 10 AES (SAP 123830).
- At affected devices the brake device will be tested and changed where required.
- Devices with Article number 58612 in combination with serial numbers 1510000 – 1529999 are affected.

Fig. 1: BLOCFOR 10 AES



Immediate action



1. Check, whether the retractable type fall arresters at hand are affected (article number in combination with serial number).
2. Do not use and block affected devices.
3. Immediately send all affected devices separately to the following address:
ENERCON Service Center Gotha GmbH
Martin Bindel
Passauer Straße 9
D-99867 Gotha
Germany
4. Alternatively other and not affected retractable type fall arresters can still be used. Also the Fallstop BK has similar characteristics and may be used.

Address any questions or issues regarding this document to the Technical Service office or local H&S staff. If necessary, they can contact the ESC Health & Safety department.

If one of the above measures results in new insights or is not appropriate and changes or additional measures become necessary, immediately notify the Technical Service office or local H&S staff.