
Types of Process Safety Indicators



Generic RCS eg PTW, Plant change, Emergency arrangements Lagging Indicators Leading Indicators

risk assessment

Critical tasks undertaken correctly % statutory inspections completed eg PTW isolations, plant change to time

% audits completed to time

Programme

Indicators

Leading Indicators

% audit actions closed out on time

% staff trained to specified competence

% procedures up date etc