



Airswab event No
83399
Date of event
23 February 2016
Alert issue date
24 February 2016
Issued by:
Name
D Fotheringham
Contact No
01383 422343
Site
Rosyth
Location
PWLS Flight Deck
Distributed to
Whole site & M&T via bulletin service

Title
PWLS - Electric Shock
Description of Incident
Injured person (IP) identified poor cable management on his POWSA and in attempting to reposition the 415v supply that was lying in water on the deck, they received an electric shock.

Photo shows 415v supply lying in water
Hazards
<ul style="list-style-type: none"> • Electricity • Water
Risks
<ul style="list-style-type: none"> • Electrocutation/Electric Shock/Death
Immediate control measures
<ul style="list-style-type: none"> • IP was treated in the Medical Centre and transferred to hospital for observation – They were later released without issues. • Electric cable was isolated and removed from area. • Contractor issued a safety brief to workforce.
Action Required
<ul style="list-style-type: none"> • Initial fact finding investigation is underway.

Ref: ROS079 24/02/2016
DISPLAY UNTIL 24/03/2016

Page 1 of 1	Revision 2	HSE(MT)-TEM-001
UNCONTROLLED IF PRINTED <i>It is the responsibility of the user to ensure they are working with the latest revision</i>		Printed: 01/03/2016