



UKOPA PIPELINE FAULT DATABASE



Pipeline Product Loss Incidents

(Up to end of 1998)

1st Report of the UKOPA Fault Database Management Group

Comprising:

BG Transco
BP Amoco
Huntsman ICI
Shell UK

Report prepared by Advantica Technologies Ltd. on behalf of FDMG



Copyright © November 2000 by Fault Database Management Group (FDMG):

This report is copyright and may not be reproduced in whole or in part by any means without the approval in writing of FDMG.

Comments, questions and enquiries to this publication should be directed to the UKOPA Pipeline Fault Database Project Manager:

Ray Hicks (Project Manager)
Pipeline Services
Advantica
Ashby Road
Loughborough
LE11 3GR

Tel: (01509) 282734
e-mail: ray.hicks@advanticatech.com

Summary

This interim report presents collaborative pipeline and fault data from BG Transco, Shell UK, BP Amoco and Huntsman ICI for operating experience up to the end of 1998 for Major Accident Hazard Pipelines (MAHPs) within their onshore high pressure steel transmission systems. The incident data presented here is for reported incidents on pipelines, within the public domain and not within a compound, where there was an unintentional loss of product from the pipeline.

A further report will cover predicted failure frequencies based on models of the growth of non product loss defect.

Contents

1	INTRODUCTION	1
1.1	BACKGROUND.....	1
1.2	PURPOSE OF THE DATABASE	1
1.3	KEY ADVANTAGES	2
2	DESCRIPTION.....	3
3	DATABASE CONTENT	5
3.1	PIPELINE SYSTEM DATA	5
3.1.1	<i>Exposure</i>	<i>5</i>
3.1.2	<i>Transported Products</i>	<i>6</i>
3.2	PRODUCT LOSS INCIDENT DATA	6
3.2.1	<i>Incident Ignition.....</i>	<i>7</i>
3.2.2	<i>Incident Frequency</i>	<i>8</i>
3.2.3	<i>Frequency per Type of Incident</i>	<i>10</i>
3.2.4	<i>External Interference</i>	<i>13</i>
3.2.5	<i>External Corrosion</i>	<i>16</i>
3.2.6	<i>Detection.....</i>	<i>20</i>

1 INTRODUCTION

1.1 Background

One of the key objectives of UKOPA is to develop a comprehensive view on risk assessment and risk criteria as they affect Land Use Planning aspects adjacent to high hazard pipelines. The main multiplier in pipeline risk assessments is the per unit length failure rate which directly relates to the extent of risk zones adjacent to the pipelines. Regulators and consultants who carry out risk assessments for UK pipelines have generally relied on US and European data to provide the basis for deriving failure rates due to the shortage of verified published data relating to UK pipelines.

With the opportunity to pool data UKOPA decided to proceed with the setting up of a UKOPA Pipeline Damage Database during May 1998. A steering group called the Fault Database Management Group (FDMG) was established to define the requirements and to direct the development of the database. This FDMG currently comprises representatives from four companies; BG Transco, Huntsman ICI, BP Amoco and Shell UK. The Health & Safety Executive also support the initiative and are in the process of joining the group.

BG Technology was selected to set-up and manage the database on behalf of UKOPA during November 1998. Development of the database was carried out during 1999 and input database 'empty shells' were issued to the participating companies to populate with their own pipeline and fault data. BG Technology pooled the company data into one collaborative database and this report presents the first set of incident data, from the collaborative data, for pipeline incidents resulting in the unintentional release of product (leak database). It is the intention of the group to publish the results of the predictive modelling, using all pipeline damage data, in 2001.

1.2 Purpose of the Database

The purpose of the database is to:

- be able to assign best estimate failure rates to a UK pipeline for risk assessment purposes based on UK pipeline damage data
- estimate leak and pipeline rupture frequencies to a UK pipeline, based on UK pipeline failure rate data
- provide a more realistic and rigorous approach to the design and routing of pipelines
- test design intentions to determine the effect of engineering changes (e.g. wall thickness of pipe, depth of burial, diameter, protection measures, inspection methods and frequencies, design factor, etc.)

1.3 Key Advantages

Setting up a new database allows UK pipeline operators to design the database such that it can be used in the most effective way based on their pipeline systems. The capability for the damage data to be processed using predictive models is a way of effectively extending the base data on which the various failure rates are calculated. One of the problems with creating a UK-only database has been the relatively limited population of pipelines and operating experience compared to large databases such as EGIG and CONCAWE. However, by considering all types of pipeline damage, not just leaks and ruptures, and extrapolating to the probability of a leak, the extent of the database can be extended to give a more comprehensive failure frequency profile.


2 DESCRIPTION

The collaborative database has been developed as a Microsoft Visual Basic 5 32-bit executable program using Microsoft Access 97 database files for data storage. ‘Empty shell’ Input Databases have been created for each contributing company to input their own pipeline and fault data.

Users of the application can carry out functions such as the addition, modification, deletion and viewing of pipelines and faults using a series of on-screen forms.

Example screens of the two parts of the database are shown below:

1. Pipeline Input Database – Example Screen



The screenshot shows a software form titled "Add New Pipeline (Step 2 of 11)". It contains several input fields and tables. On the right side, there are three buttons: "Next >", "< Previous", and "Cancel".

Fields include:

- Pipe name (max. 60 characters)
- Transported Product (dropdown menu)
- Product Phase in Pipeline (dropdown menu)
- Outside Diameter (mm)
- Nominal Wall Thickness (mm)
- Other Wall Thickness (mm)


Wall Thickness	Length (km)

Below this is a section for "Pipe Manufacturer" with a table:

Manufacturer	Length (km)
British Steel	
Italsider	
Mannesmann	
Stuarts and Lloyds	
Thyssen	
Unknown	

At the bottom, there is a text field: "If Other please specify (max. 40 chars)".

2. Fault Input Database – Example Screen



The screenshot shows a software form titled "Add New Fault (Step 5 of 7)". It contains several input fields and tables. On the right side, there are three buttons: "Next >", "< Previous", and "Cancel".

Fields include:

- Internal Coating at the Fault (dropdown menu)
- If Other please specify (up to 40 characters)

Defect details table:

Type of Defect	Length (mm)	Width (mm)	Depth (mm)	Orientation (degrees)

Inspection Details table:

Type of Inspection	Date
CIPS/Pearson	
Land Owner	
OLI	
Visual	
Other	

At the bottom, there are two text fields: "If Other please specify (up to 40 characters)" and "Additional Comment (up to 100 characters)".




Each company has populated its input database with operating experience up to the end of 1998 and returned the data (.mdb file) to BG Technology for collation and analysis. This process is intended to be carried out on a regular basis and results from the collaborative database will also be published on a regular basis. The next update will be carried out during 2001 and will include pipeline and fault data for 1999 and 2000.

3 DATABASE CONTENT

3.1 Pipeline System Data

3.1.1 Exposure

The total length of the pipeline system (MAHPs), above ground, below ground and elevated, up to the end of 1998 for all participating companies (BG Transco, BP Amoco, Shell UK, Huntsman ICI) is 20,045 km. The exposure in the period 1952 to end 1998 is 518,818 km.yr, as illustrated in Figure 1.



Length of Pipeline which has unknown commissioning date = 44.8km. (This has been ignored in the exposure calculations)

Exposure to end 1998 of Elevated Pipeline = 17.9km.yr (included in totals)

Exposure to end 1998 of Above Ground Pipeline = 102.4km.yr (included in totals)

Figure 1

3.1.2 Transported Products

The transported products include (km):

Butane	19.5	Propylene	36.3
CO	36.3	LPG	9.6
Condensate	24	Natural Gas (Dry)	18,333
Crude Oil (Spiked)	212.6	Other	225.8
Ethane	38.1	Propane	19.5
Ethylene	1045.5	TOTAL	20,000

Although the UKOPA database currently comprises only MAHPs, the intention is to include non-MAHPS in the future.

3.2 Product Loss Incident Data

The criteria for a product loss incident on a pipeline are:

- within the public domain and outside the fences of installations
- excluding associated equipment (e.g. valves, compressors) or parts other than the pipeline itself
- there was an unintentional loss of product from that pipeline

A total of 161 product loss incidents were recorded over the period between 1962 and 1998. No product loss incidents were recorded prior to 1962. An annual breakdown of incidents is illustrated in Figure 2.a. The cumulative number of incidents over the period 1962 to 1998 is shown in Figure 2.b.




Figure 2a




Figure 2b

3.2.1 Incident Ignition

There were 8 out of 161 (5%) product loss incidents that resulted in ignition. Table 1 below provides more detail:

Affected Component	Cause Of Fault	Hole Diameter Class
Pipe	Seam Weld Defect	0-6mm
Pipe	Ground Movement	Full Bore (18" Diameter Pipe)
Pipe	Girth Weld Defect	6-20mm
Pipe	Pipe Defect	0-6mm
Pipe	Unknown	50 ⁺ mm
Pipe	Lightning Strike	0-6mm
Bend	Internal Corrosion	0-6mm
Bend	Unknown	6-20mm

Table 1 – Incidents that Resulted in Ignition

3.2.2 Incident Frequency

The incident frequency over consecutive 5-year periods is given in Table 2.

Period	Number of Incidents	Total Exposure [km.yr]	Frequency [Incidents per 1000 km.yr]
1960-1964	5	7,030	0.711
1965-1969	15	25,980	0.577
1970-1974	25	58,482	0.427
1975-1979	23	73,200	0.314
1980-1984	34	84,620	0.402
1985-1989	36	91,430	0.394
1990-1994	16	96,538	0.166
1994-1998	9	99,730	0.090

Table 2

The overall incident frequency by hole size over the period 1960 – 1998 is given in Table 3.

Hole Size Class	Number of Incidents	Frequency [Incidents per 1000 km.yr]
Full Bore*	6	0.012
≥ 50mm	16	0.031
≥ 20mm	38	0.073
≥ 6mm	57	0.110
0 – Full Bore	161	0.311

Table 3

* Full Bore = diameter of pipeline

The failure frequency over the last 5 years (1994-1998) is 0.090 incidents per 1000km.yr as compared to the overall failure frequency during the period 1960-1998 which is 0.311 incidents per year per 1000 km of pipeline. An overview of the development of this overall failure frequency over the total period of 1960 to 1998 is given in Figure 3. This figure shows the change in the incident frequency in each year being the cumulative total from 1960 onwards. In order to see the results over the last period, without influence of the past, the moving average is calculated only over the past 5 years (1960-1964, 1961-1965, 1962-1966, etc).




Figure 3

3.2.3 Frequency per Type of Incident

Product Loss Incident Frequency by Cause is given in Figure 4.




Figure 4

Product Loss Cause	No. of Incidents
Girth Weld Defect	33
External Interference	31
Internal Corrosion	27
External Corrosion	26
Unknown	12
Other	12
Pipe Defect	12
Ground Movement	5
Seam Weld Defect	3
Total	161

Table 4 – No. of Product Loss Incidents by Cause



Figure 5 shows the frequency per type of product loss incident (initiating cause) over the period 1960-1998 compared with the frequency over only the last 5 years (1994-1998).





Figure 5



An overview of the product loss incident frequency by cause and size of leak in the period 1952 to 1998 is given in Figure 6.



Construction/Material = Seam Weld Defect + Pipe Defect + Pipe Mill Defect + Damage During Original Construction

Figure 6

3.2.4 External Interference

Figure 6 shows that external interference is one of the main causes of product loss incident data.

3.2.4.1 External Interference per Diameter Class

In Figure 7 the product loss incident frequencies associated with external interference are given per diameter class and by hole size.





Figure 7

Diameter	Exposure	Incidents
0-4	28708	4
5-10	106402	14
12-16	91236	6
18-22	80299	3
24-28	86976	3
30-34	25982	1
36-48	99214	0
Total	518,818	31

Table 5 – Exposure per Diameter Class in km.yr

3.2.4.2 External Interference per Measured Wall Thickness Class

The relationship between product loss incidents caused by third party interference (outside forces on the pipeline) and the wall thickness is shown in Figure 8.



Nb: Maximum wall thickness for loss of product incident caused by external interference is 12.7mm.

Figure 8

Wall Thickness	Exposure	Incidents
<5	42222	10
5-10	250030	17
10-15	192558	4
>15	34006	0
Total	518,816	31

Table 6 – Exposure by Wall Thickness Class in km.yr

3.2.4.3 External Interference per Area Classification




Figure 9

Area Classification	Exposure	Incidents
Rural	443,447	24
Suburban + Semi-rural	46,060	7
Urban	518	0
Total	490,025	31

Table 7 – Exposure by Area Classification in km.yr

Nb:

Rural = population density < 2.5 persons per hectare

Suburban and Semi-rural = population density > 2.5 persons per hectare and which may be extensively developed with residential properties

Urban = Central areas of towns or cities with a high population density

3.2.5 External Corrosion

3.2.5.1 External Corrosion per Wall Thickness Class




Figure 10

Wall Thickness	Exposure	Incidents
<5	42222	15
5-10	250030	11
10-15	192558	0
>15	34006	0
Total	518,816	26

Table 8 – Exposure by Wall Thickness Class in km.yr

3.2.5.2 External Corrosion per Year of Construction




Figure 11

Construction Year	Exposure	Incidents
Pre-1964	68546	16
1964-1973	330066	10
1974-1983	94187	0
1984-1993	25530	0
1994-1998	488	0
Total	518,818	26

Table 9 – Exposure by Year of Construction in km.yr

3.2.5.3 External Corrosion per External Coating Type




Figure 12

External Coating	Exposure	Incidents
Bitumen	20063	2
Coal Tar	417077	18
Polyethylene	31302	1
FBE	27525	0
Other/Unknown	22861	5
Total	518,828	26

Table 10 – Exposure by External Coating Type in km.yr

3.2.5.4 External Corrosion per Type of Backfill




Figure 13

3.2.6 Detection




Figure 14