

UKOPA

United Kingdom Onshore Pipeline Operators' Association

An aerial photograph showing a large-scale pipeline construction project. A massive, light-colored pipe section is being laid out on a dirt road. Several yellow excavators and other heavy machinery are visible along the road, working on the construction. The scene is set in a rural area with green fields and some buildings in the background.

UKOPA Third Party Infringement Working
Group

Status October, 2011

2010 3rd Party Infringement Report : Worst Infringers Table

Infringement Category	A1		B1		B2		C1		C2		Total Score
Balfour Beatty	0		3		1		4		1		136
Clugstone	1		0		0		0		0		100
Morrison Utilities	0		1		1		3		1		66
National Grid	0		1		1		3		1		66
United Utilities	0		2		1		0		0		65
Wind Prospects	0		2		1		0		0		65
Metro Demolition	0		2		0		0		0		60
Skanska/BB	0		0		0		5		0		50
Enterprise	0		1		0		1		2		42
Morrison Construction	0		0		0		4		0		40
David Websters	0		1		2		0		0		40

Infringement Working Group Challenges

Difficulties in infringement data collection continue into 2011.

Problems in collecting the results for the report is leading to delays in generating any improvement actions.

Convening an IWG meeting in the second half of 2011 has proved difficult.

Agreement of how best to use the data to improve performance

Infringement Working Group

Forward Plan for 2011/2012

IWG meeting arranged for 3rd November in Tebay

Target the Worst Infringers at Senior Management Level

Further Improve the infringement data supplied from the members

Raise the profile of the UKOPA Infringement Report

Fisher German Proposal to be considered