


# UKOPA

United Kingdom Onshore Pipeline Operators' Association

An aerial photograph of a pipeline construction site. A large, white pipe section is being lowered into a deep trench. Several yellow excavators and trucks are visible on the dirt road next to the trench. The background shows a grassy field and some buildings.

UKOPA Third Party Infringement Working  
Group

Status October, 2011

### 2010 3<sup>rd</sup> Party Infringement Report : Worst Infringers Table

Infringement Category	A1		B1		B2		C1		C2		Total Score
Balfour Beatty	0		3		1		4		1		136
Clugstone	1		0		0		0		0		100
Morrison Utilities	0		1		1		3		1		66
National Grid	0		1		1		3		1		66
United Utilities	0		2		1		0		0		65
Wind Prospects	0		2		1		0		0		65
Metro Demolition	0		2		0		0		0		60
Skanska/BB	0		0		0		5		0		50
Enterprise	0		1		0		1		2		42
Morrison Construction	0		0		0		4		0		40
David Websters	0		1		2		0		0		40

### **Infringement Working Group Challenges**

Difficulties in infringement data collection continue into 2011.

Problems in collecting the results for the report is leading to delays in generating any improvement actions.

Convening an IWG meeting in the second half of 2011 has proved difficult.

Agreement of how best to use the data to improve performance

### **Infringement Working Group**

### **Forward Plan for 2011/2012**

IWG meeting arranged for 3<sup>rd</sup> November in Tebay

Target the Worst Infringers at Senior Management Level

Further Improve the infringement data supplied from the members

Raise the profile of the UKOPA Infringement Report

Fisher German Proposal to be considered