

**Airsweb event No****85746****Date of event****10 June 2016****Issue date****19 July 2016****Issued by****D Fotheringham****01383 422343****Rosyth****Location****Rampion Hard Standing****Distributed to****Whole site & M&T via bulletin service**

LEARNING FROM EXPERIENCE

Title

Working at Height Incident

Description

- Two individuals were working on top of a platform inside of a scaffolding South of the Build Hall, one individual stepped through the scaffolding edge protection in order to manually handle some sheeting. Individual not was wearing a harness or any fall arrest equipment.
- No one was injured.



Photo showing area personnel were standing

Key Learning

- Workers in the area were stood down and briefed regarding the issue.
- Personnel were disciplined in accordance with company procedures and reminded any future breaches will result in dismissal.
- Personnel to attend working at height presentation – Jason Anker.
- Working at height posters displayed in area.

Recommendations for dissemination:

- Toolbox talk
- Time Out For Safety (TOFS)
- Safety stand down
- Bulletin